MS MPx Firmware – Release Notes

Version 8.16.0 30/10/206

Hash: A8FF3193BA568D8778EA251653F6C78075D9AD2F4DF9DF74464A30778EA368FE

MP-series e JP4-revamping-katana WF update

Vacuum labels on IO module

Meteor Sybsystem Failure! [013b0] handled

version 8.14.3 - 10/2/2026

Hash 75E565CF75B946B5408F9593AFAE5C6BCB4AA3E2AB472ECF4BA00F8DE34B7E78

Default values of parameters shown in web page

installed waveform list visualization and waweform import on web page

fix of poweron time while resetting it

acustic signal on print break

CCR of CAN drive

wiping positions menu enhanched

added acustic signal on print break

Version 8.08.09 – 23/07/2026

Add light color to headtemp graph

fix wrong M and N modalities for MPK 2CMYK printers

fix Meter counter counts in negative on MP3100

Version 8.08.06 – 07/07/2026

change strings for MP external devices

remove http temperature value if heads are poweroff

fix problem on headtemp change day

Version 8.06.10 – 18/06/2026

fix bug when switch to torque with ext unw it remain. On MP5000 switch between Unwinder Built in → External now works

Version 8.06.09 – 22/05/2026

add HBL 6.7.4 support to fix Meteor error message while early abort command

Version 8.06.08 – 19/05/2026

Fixed the buzzer that never stops ringing

Version 8.06.07 – 18/05/2026

invert bars and remove white spaces

Version 8.06.06 – 11/05/2026

insert lock for meteor operations

From develop 8.07.062

Version 8.06.05 – 08/05/2026

remove disable UI during spitting on idle

restore “READY” message on interface

Version 8.04 – 02/03/2026

- First Release compatible with MP Series printers