

# MS MPx Firmware – Release Notes

## **version 8.14.3 - 10/2/2026**

*Hash 75E565CF75B946B5408F9593AFAE5C6BCB4AA3E2AB472ECF4BA00F8DE34B7E78*

Default values of parameters shown in web page

installed waveform list visualization and waveform import on web page

fix of poweron time while resetting it

acoustic signal on print break

CCR of CAN drive

wiping positions menu enhanced

added acoustic signal on print break

## **Version 8.08.09 – 23/07/2026**

Add light color to headtemp graph

fix wrong M and N modalities for MPK 2CMYK printers

fix Meter counter counts in negative on MP3100

## **Version 8.08.06 – 07/07/2026**

change strings for MP external devices

remove http temperature value if heads are poweroff

fix problem on headtemp change day

## **Version 8.06.10 – 18/06/2026**

fix bug when switch to torque with ext unw it remain. On MP5000 switch between Unwinder Built in → External now works

## **Version 8.06.09 – 22/05/2026**

add HBL 6.7.4 support to fix Meteor error message while early abort command

## **Version 8.06.08 – 19/05/2026**

Fixed the buzzer that never stops ringing

## **Version 8.06.07 – 18/05/2026**

invert bars and remove white spaces

**Version 8.06.06 – 11/05/2026**

insert lock for meteor operations

From develop 8.07.062

**Version 8.06.05 – 08/05/2026**

remove disable UI during spitting on idle

restore “READY” message on interface

**Version 8.04 – 02/03/2026**

- First Release compatible with MP Series printers