

MS MPx Firmware – Release Notes

Version 8.06.09 – 22/05/2026

add HBL 6.7.4 support to fix Meteor error message while early abort command

Version 8.06.08 – 19/05/2026

Fixed the buzzer that never stops ringing

Version 8.06.07 – 18/05/2026

invert bars and remove white spaces

Version 8.06.06 – 11/05/2026

insert lock for meteor operations

From develop 8.07.062

Version 8.06.05 – 08/05/2026

remove disable UI during spitting on idle

restore “READY” message on interface

Version 8.04 – 02/03/2026

- First Release compatible with MP Series printers